

Annexure D

BUILDING SAFETY CERTIFICATE

NO. 148

Dated: 06.02.2025

It is Certified that the existing building **NPS GURUKULAM PUBLIC SCHOOL**(name of the building or premises) at **SIRHE, P.O.- NAWADA, P.S.- MERAL, DIST.- GARHWA** (address) is having block(s)/Floor(s) as per below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	03					

The building is owned/occupied By **NPS GURUKULAM PUBLIC SCHOOL, SIRHE, MERAL, GARHWA** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Executive Engineer, Building Division, Garhwa** (Name of Department/Govt.) on **06/02/2025** (date of inspection) in the presence of Manager/Secretary **ROUSHAN SINGH, Vill&P.O.-MORBEY, P.S.- MANJHIAON, DIST.- GARHWA** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **05/02/2026** for a period of **01 (One) Year** in accordance with rule and subject to compliance of the specific conditions as appended.

1. /
2. /
3. /
4. /

Issued on **06.02.2025** at **B.C.D, Garhwa** by

- Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

06.02.25
Executive Engineer
Building Construction Department
Name: **PREM CHAND SINGH**
Building Division, Garhwa

Designation: **Executive Engg.**

Name & Address of Department/Office: **B.C.D. GARHWA**